



























This diagram is intended as a guide to the types of fits required to ensure the clock will run correctly. NB! All gear pairs are assembled this way, and have a set screw to hold them onto the shaft Loose Fit Tight Fit Glued

NB! The ball races may be substituted with plain bearings if required. The bearings and the domed headed nuts are proprietary items and can be obtained from the internet.

Sht15of15Shts A3	Clock 14 - Mantle Wind-up Clock	Cross section showing Fits
Scale 1:1 Unless otherwise stated	All dimensions in mm and (inchs) 3rd Angle projection	October 2012 Designed by: Brian law www.woodenclocks.co.uk